

School Facilities and Organization INFORMATION AND CONDITION OF SCHOOLS Detailed Condition Assessment by Building Reporting Year 2020-2021

PORT TOWNSEND

82.42%

BLUE HERON MIDDLE SCHOOL - MAIN BUILDING

Building Details

PROFILE TYPE Middle/Junior High School - Single Story

NUMBER OF FLOORS 1

BOARD ACCEPTANCE DATE 10/2/1995

CHARACTERISTICS Occupied

ANNUAL REVIEW COMPLETED BY District

This building is required to comply with the Asset Preservation Program

REPORTING YEAR	APP YEAR	BUILDING CONDITION ASSESSMENT	ANNUAL REVIEW COMPLETED BY	BOARD REPORT PRESENT DATE
2020-2021	25	82.42	District	Not Reported
2019-2020	24	87.70	Consultant	3/19/2020
2018-2019	23	88.29	Consultant	3/21/2019
2017-2018	22	Not Reviewed	Incomplete	Not Reported
2016-2017	21	88.29	District	3/27/2017
2015-2016	20	Not Reviewed	Incomplete	Not Reported

The next certified BCA is due: 2025

Building Inventory

AREA YEAR BUILT	DISTRICT ASSIGNED AREA	GROSS BUILDING SQ FT	GROSS INSTRUCTIONAL SQ FT	SCAP RECOGNIZED SQ FT	ORIGINAL OCCUPANCY DATE	ORIGINAL BOARD ACCEPTANCE DATE
1995	Main Building	60,124	60,124	60,124	9/4/1995	10/2/1995
	Building Totals	60,124	60,124	60,124	_	

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Foundations	Standard Foundation	A1010		90.00% Good
Slabs on Grade	Standard Slabs on Grade	A4010		90.00% Good
Water and Gas Mitigation	Building Subdrainage	A6010		90.00% Good
Superstructure	Roof Construction	B1020		90.00% Good



PORT TOWNSEND

82.42%

Detailed Condition Assessment by Building

Reporting Year 2020-2021

BLUE HERON MIDDLE SCHOOL - MAIN BUILDING

SUB-ASSEMBLY	COMPONENT	COMPONENT MAINTENANCE CODE PRIORITY	CONDITION RATING
Exterior Vertical Enclosures	Exterior Walls	B2010	90.00% Good
	Comments:	Very minor and sparse surface damage in various locations.	
	Exterior Windows	B2020	90.00% Good
	Exterior Doors and Grilles	B2050	90.00% Good
	Exterior Louvers and Vents	B2070	90.00% Good
Exterior Horizontal Enclosures	Roofing	B3010	62.00% Fair
	Deficiencies:	Other	
	Causes:	Surface Weathering	
	Comments:	Roof cleaned & minor repairs made in 2014.	
	Roof Appurtenances	B3020	90.00% Good
	Overhead Exterior Enclosures	B3080	90.00% Good
	Comments:	In this case, this component includes the entry canopy.	
Interior Construction	Interior Partitions	C1010	90.00% Good
	Comments:		
	Interior Windows	C1020	90.00% Good
	Interior Doors	C1030	62.00% Fair
	Deficiencies:	Other	
	Causes:	Other	
	Comments:	Some interior partitions don't work. Man-doors are in good shape.	
	Interior Grilles and Gates	C1040	90.00% Good
	Suspended Ceiling Construction	C1070	90.00% Good
Interior Finishes	Wall Finishes	C2010	90.00% Good
Interior Finishes	-		



PORT TOWNSEND

82.42%

Detailed Condition Assessment by Building

Reporting Year 2020-2021

BLUE HERON MIDDLE SCHOOL - MAIN BUILDING

SUB-ASSEMBLY	COMPONENT	COMPONENT MAINTENANCE CODE PRIORITY	CONDITION RATING
Interior Finishes	Comments:	Most walls repainted summer 2019.	
	Interior Fabrications	C2020	90.00% Good
	Flooring	C2030	30.00% Poor
	Deficiencies:	Irregular Surface	
	Causes:	Deterioration, Settlement	
	Comments:	Hallway VCT installed in 2009 has gaps at joints. Settlement/moisure has cracked some VCT in approximately 2% of building. Tiles schedule to be replaced summer 2021. Carpet installed in hallways in 2015.	
	Ceiling Finishes	C2050	62.00% Fair
	Deficiencies:	Cracking, Peeling, Flaking, Surface Appearance	2
	Causes:	Surface Damage	
	Comments:	Stains and some warping on a few ceiling tiles.	
Plumbing	Domestic Water Distribution	D2010	90.00% Good
	Deficiencies:	Other	
	Causes:	Lack of Insulation, Other	
	Comments:	Replaced 3 water heaters in past five years.	
	Sanitary Drainage	D2020	90.00% Good
	Building Support Plumbing Systems	D2030	90.00% Good
IVAC	Facility Fuel Systems	D3010	90.00% Good
	Heating Systems	D3020	90.00% Good
	Facility HVAC Distribution Systems	D3050	90.00% Good



PORT TOWNSEND

82.42%

Detailed Condition Assessment by Building

Reporting Year 2020-2021

BLUE HERON MIDDLE SCHOOL - MAIN BUILDING

SUB-ASSEMBLY	COMPONENT	COMPONENT MAINTENANCE CODE PRIORITY	CONDITION RATING
HVAC	Comments:		
	Ventilation	D3060	90.00% Good
	Comments:		
Fire Protection	Fire Suppression	D4010	90.00% Good
	Fire Protection Specialties	D4030	90.00% Good
Electrical	Facility Power Generation	D5010	90.00% Good
	Electrical Services and Distribution	D5020	90.00% Good
	General Purpose Electrical Power	D5030	90.00% Good
	Lighting	D5040	90.00% Good
	Comments:	Upgraded to LED lighting in Gym in past year.	
Communications	Data Communications	D6010	100.00% Excellent
	Voice Communications	D6020	100.00% Excellent
	Comments:	New VOIP system installed in 2015.	
	Audio-Video Communications	D6030	90.00% Good
	Distributed Communications and Monitoring	D6060	90.00% Good
	Comments:	New VOIP system installed in 2015. Speakers upgraded recently.	
Electronic Safety and Security	Access Control and Intrusion Detection	D7010	90.00% Good
	Comments:	Working, but not enough coverage.	
	Electronic Surveillance	D7030	100.00% Excellent
	Comments:	2017 and 2019 additional cameras have been installed to existing roster.	
	Detection and Alarm	D7050	0.00% Unsatisfactory



PORT TOWNSEND

82.42%

Detailed Condition Assessment by Building

Reporting Year 2020-2021

BLUE HERON MIDDLE SCHOOL - MAIN BUILDING Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT MAINTENANCE CODE PRIORITY	CONDITION RATING
Electronic Safety and Security	Deficiencies:	Other	
	Causes:	Other	
	Comments:	FA panels need to be replaced - planned in 2020 or 2021. System is currently addressable.	
Integrated Automation	Integrated Automation Facility Controls	D8010	100.00% Excellent
Equipment	Commercial Equipment	E1030	90.00% Good
	Institutional Equipment	E1040	90.00% Good
	Entertainment and Recreational Equipment	E1070	62.00% Fair
	Deficiencies:	Other	
	Causes:	Equipment Obsolescence	
	Comments:	Some systems out of date due to age of system & normal wear & tear. 2019 some has been upgraded.	
	Other Equipment	E1090	90.00% Good
Furnishings	Fixed Furnishings	E2010	62.00% Fair
	Deficiencies:	Surface Deterioration	
	Causes:	Surface Water	
	Comments:	Age is a factor.	